Haasco, Ltd.

147 First Avenue East Post Office Box 156 Dyersville, Iowa 52040 563-875-8300



2020 AHERA Re- Inspection

Table of Contents

Introduction	1
Anamosa High School	2
- Exterior Buildings- Fitness Center (New 2003)- New Addition	
Former Anamosa Middle School site Now Central Administration and Maintenance Building	3
Strawberry Hill Elementary School Exterior Buildings	4
Miscellaneous Locations	5
New Middle School Exterior Buildings	6

Introduction

Anamosa Community School District

AHERA REINSPECTION List of Buildings

2) Anamosa High School Anamosa, Iowa

Exterior Buildings:

New addition — Letter of Exclusion enclosed Wood Storage Shed: No ACBM 2 small storage buildings — practice football field New Activity Center -Letter of Exclusion enclosed

3) Anamosa Middle School Building- demolished 2014 Anamosa, Iowa -now Maintenance Building

Central Administration -Letter of Exclusion enclosed

4) Strawberry Hill Elementary School

Anamosa, Iowa

1998 Building Addition- Letter of Exclusion enclosed Single Car Garage

Concession stand –NE of the school – Letter of Exclusion enclosed Storage buildings (2) fields behind school – none 8' x 12' portable –vinyl - west side of school – none

5) Miscellaneous Locations

Anamosa, Iowa

Football Field

Eden Field

Bus Barn

Raider Softball Field

6) New Middle School- Letter of Exclusion enclosed New sport buildings _ Letter of Exclusion enclosed Football storage – Letter of exclusion enclosed November 2020

Designated Person

The attached material is the AHERA Reinspection report for your school district. The re inspection was completed by Thomas E. Haas of Haasco, Ltd., a State of Iowa licensed Asbestos Inspector/Management Planner, license and training certificates enclosed

Friable materials which are now non-friable as a result of repairs, enclosures, or encapsulation activities are now updated to a non-friable status. Any materials which are friable are listed as such. A physical assessment and a hazardous assessment have been completed for all friable materials.

A list of needed responses has been completed on the enclosed sheets. The starting and completion dates are listed on the individual assessments. All areas of friable materials need initial cleaning prior to response actions.

Any additional information can be found located in the original AHERA Inspection. Asbestos-containing materials that have been abated or analyzed as non asbestos-containing materials prior to this re inspection have been eliminated from this report. This method was used to simplify and clarify the remaining materials for those individuals who need this information. The management program is an on going process which constantly changes and can be updated in this same manner to keep it an accurate picture of the facilities.

If floor tiles were sampled and analyzed using Polarized Light Microscopy (PLM) and identified as non asbestos-containing on the original inspection, the Environmental Protection Agency (EPA) now recommends retesting the floor tiles using Transmission Electron Microscopy (TEM), which is more accurate.

The Inspector/Management Planner has not reviewed the adequacy of the existing Management Plan, nor has he made any independent judgments of previous inspection reports, sampling protocol or sample analysis other than listed in this Re inspection Report. Any errors and/or omissions in asbestos related work done prior to this Re inspection is strictly the responsibility of the school district.

The school district acknowledges that they are aware of the various asbestos related services provided by Haasco, Ltd., and has considered any possible conflict of interest which might arise, and has acquired services which are in the best interest of the school district. An example of a possible conflict of interest would be Thomas E. Haas, acting as the Management Planner, recommends removal, and then Thomas E. Haas, acting as the Asbestos Removal Contractor, would do the removal.

To comply with AHERA, place a copy of the AHERA Re inspection Report/Management

Plan in each administrative offices and a copy in the Superintendent's office.

If there are any questions, feel free to contact our office at your convenience.

Thomas E. Haas

Inspector/Management Planner

Cost		\$150.00	\$150.00	\$100.00
Damage-amount classification Recommendation Distributed/Localized		Repair and clean up debris by Sept 2021	Repair by Sept 2021 above SCT center of room	Repair by Sept 2021
Classification		Damage	Damage	Damage
Damage-amount Frequency Vibration Distributed/Localized		Low <10%	low <10%	low <10%
Frequency V	-	low	wol	wol
Assessment Accessibility		wol	low	low
Location , Material ,		Mudded joints	Mudded joints	Mudded Joint
Building	High School	Kitchen	Room 120	Storage between art rooms Mudded joint

Asbestos clarifications concerning AHERA and NESHAP Asbestos Regulations

AHERA was a regulation enacted by the EPA (1986) and address asbestos in schools. The rule required schools to inspect the interior portions of the buildings, covered exterior walk ways and exterior mechanical systems that heated and cooled interior spaces. Under the rule, schools could either sample materials, or assume that they contain asbestos.

- (a) Under AHERA, a building built after 1987 could be exempt from the AHERA requirements, if an architect or an asbestos inspector signed a statement that it was built after 1987 and no construction document specified the use of asbestos.
- (b) If all asbestos identified on the original inspection was abated, then the school was not required to continue doing 3 year asbestos re inspection, etc. unless asbestos containing materials were discovered.

There were additional requirement which the school needed to do to comply under the AHERA (school) rule.

Schools are required to comply with both the AHERA (school) and NESHAP asbestos rules (public).

Under NESHAP, there is no exemption for when a building was built. If you are going to renovate or demolish a building, you are required to do an asbestos inspection. In addition, having a statement that all asbestos was abated, prior to a complete inspection, will not meet the NESHAP standard.

So you decide to demolish a building or renovate and have a statement that all asbestos was abated under the AHERA rule, here are some of the problems:

- 1. Do you have the original sample results that show that asbestos is not present in all of the suspect materials?
- 2. Under AHERA, only interior suspected asbestos materials were listed, no exterior roofing, caulking around doors, windows, transite panels above windows, etc. NESHAPS requires all suspect asbestos materials to be tested
- 3. Under AHERA only the material listed on the original inspection was required to be looked at on the 3 Year Re Inspections. As a result, if materials were missed or not listed on the original inspection, they were not required to look at on the 3 year re inspection.

- 4. On the original AHERA inspection, the inspector most likely had a condition listed where he stated that interior of boilers, adhesives, caulks, concealed items were not addressed on the inspection and were assumed to contain asbestos. These items will now be required to be tested.
- 5. Many items that contain asbestos were missed on the original inspection due to lack of knowledge or a poor inspection.
- 6. Materials that were not suspect asbestos containing materials in 1987 are now considered suspect. (Terrazzo, black counter, table tops, mortar, etc.).
- 7. Since the original inspection (1987) areas have been remodeled and new materials have been installed. All of these materials need to be tested under the NESHAP rule.

Under the original AHERA inspection a destructive inspection could not be done. Blackboard could not be removed to check for adhesives, panels glued to wall could not be tested which out damaging the walls, etc.

This memo is only meant to assist you to understand both the AHERA and NESHAP rules concerning asbestos. For additional and detail information refer to the regulations.

This is only some of the issues that you face when demolishing or renovating a building. For more information, you can contact the IDNR, asbestos section or Iowa OSHA.

Thomas E. Haas

 License Type
 Number
 Expires

 INSPECTOR
 20-3704
 01-04-2021

 MANAGEMENT PLANNER
 20-3705
 01-04-2021

 PROJECT DESIGNER
 20-3706
 01-06-2021



Rod A. Roberts Labor Commissioner

1

THOMAS HAAS

DOB: 12-24-1948 Issued: 01-15-2020



This person is licensed to perform asbestos work in the State of lowa. ID card is intended for official use only and must be present on jobsite.

Designated Person Responsibilities and Information

Designated Person Information

Anamosa Community School Designated Person is Tom Rogers. You can contact him by calling the Anamosa Central Administration office

I, the Designated Person for the School District certify in this statement that to the best of my knowledge, the LEA responsibilities, as stipulated by 763.84, have been met.

I, the Designated Person for the school district certify that the school district acknowledges that they are aware of the various asbestos related services provided by outside Asbestos Contractors, and has considered any conflict of interest which might arise from the interrelationship between accredited personnel, and has acquired services which are in the best interest of the school district. An example of a possible conflict of interest would be if the outside Asbestos Contractor, acting as the Asbestos Inspector/ Management Planner, recommends removal, and then the same Asbestos Contractor does the asbestos removal.

AHERA Designated Person Statement

The AHERA Designated person has met (or will meet) the responsibilities below.

Per 40 CFR Part 763 Asbestos-Containing Materials in Schools; Final Rule and Notice; the following is a list of Local Education Agency (LEA) responsibilities:

- 1) 763.84(a) Ensure that the activities of any persons who perform inspections, re inspections, and periodic surveillance develop and update management plans, and develop and implement response actions, including operations and maintenance, are carried out is accordance with Subpart E of this part.
- 763.84(b) Ensure that all custodial and maintenance employees are properly trained as required by this Subpart E and other applicable Federal and/or State regulations (e.g., the Occupational Safety and Health Administration asbestos standard for construction, the EPA worker protection rule, or applicable State regulations).
- 3) 763.84(c) Ensure that workers and building occupants, or their legal guardians, are informed at least once each school year about inspections, response actions, and post-response action activities including periodic re inspections and surveillance activities that are planned or in progress.
- 4) 763.84(d) Ensure that short-term workers (e.g., telephone repair workers, utility workers, or exterminators) who may come in contact with asbestos in a school are provided information regarding the locations of ACBM and suspected ACBM, and/or assumed ACM.
- 5) 763.84(e) Ensure that warning labels are posted in accordance with 763.95.
- 6) 763.84(f) Ensure that management plans are available for inspection and

- notification of such availability has been provided as specified in the management plan under 763.93(g).
- 7) 763.84(g)(1) Designate a person to ensure that requirements under this section are properly implemented.
- 8) 763.84(g)(2) Ensure that the Designated Person receives adequate training to perform duties assigned under this section. Such training shall provide, as necessary, basic knowledge of:
 - (i) Health effects of asbestos.
 - (ii) Detection, identification, and assessment of ACM.
 - (iii) Options for controlling ACBM.
 - (iv) Asbestos management programs.
 - (v) Relevant Federal and State regulations concerning asbestos, including those in this Subpart E and those of the Occupational Safety and Health Administration, U.S. Department of Labor, the U.S. Department of Transportation and the U.S. Environmental Protection Agency.
- 9) 763.84(h) Consider
- 10) Whether any conflict of interest may arise from the interrelationship between accredited personnel and whether that should influence the selection of accredited personnel to perform activities under this subpart.

Designated Persons/Signature

Date

Designated Person Responsibilities

- 1) 763.87(d) Ensure that bulk material sample analysis results include the name and address of each laboratory performing an analysis, the date of analysis, the name and signature of the person performing the analysis and that these analysis reports are included in the LEA's Management Plan within thirty (30) days of the analysis,
- 2) 763.88(d) Ensure that persons performing inspections, reinspections, assessments, recommendations and other asbestos related services are accredited and that these are included in the LEA's Management Plan,
- 3) 763.92(b)(2)(iii) Ensure that periodic surveillance reports are included in the LEA's Management Plan,
- 4) 763.93(e)(4) Ensure the LEA's Management Plan contains the LEA's Designated Person's name, address and telephone number along with courses completed, the dates and hours of training taken by that person to carry out the duties,
- 5) 763.93(i) Include in the LEA's Management Plan a true and correct statement, signed by the Designated Person which certifies that the general, local education agency responsibilities, as stipulated by 763.84, have been met or will be met.

LEA and DESIGNATED PERSON RESPONSIBILITIES

The following is a list of Local Education Agency responsibilities:

- 1) Ensure that all inspections, re inspections, periodic surveillances, the management plan, development and updating, response actions, and development and implementation of operation and maintenance activities are performed in accordance with EPA's Asbestos-Containing Materials in Schools regulation (40 CFR 763 Subpart E).
- 2) Ensure proper training for all custodial and maintenance employees as required by all federal and state regulations.
- 3) Ensure that all workers and building occupants, or their legal guardians, are informed about all inspections, re inspections, periodic surveillances activities and response actions that are planned or in progress. Notification must be at least once every school year.
- 4) Ensure that all short term workers who may come in contact with asbestos are notified of the locations of ACBM, suspected ACBM, and/or assumed ACM.
- 5) Ensure the availability of the management plans for inspections and re inspections and provide notification of such availability.
- 7. Consider if any conflict of interest may arise from the interrelationship between accredited personnel and others that could affect the designation of a person to carry out the LEA's responsibilities.
- 8) Designated a person to ensure these responsibilities are implemented.

LEA and DESIGNATED PERSON RESPONSIBILITIES

The following is a list of Local Education Agency responsibilities:

- 1) Ensure that all inspections, re inspections, periodic surveillances, the management plan, development and updating, response actions, and development and implementation of operation and maintenance activities are performed in accordance with EPA's Asbestos-Containing Materials in Schools regulation (40 CFR 763 Subpart E).
- 2) Ensure proper training for all custodial and maintenance employees as required by all federal and state regulations.
- 3) Ensure that all workers and building occupants, or their legal guardians, are informed about all inspections, re inspections, periodic surveillances activities and response actions that are planned or in progress. Notification must be at least once every school year.
- 4) Ensure that all short term workers who may come in contact with asbestos are notified of the locations of ACBM, suspected ACBM, and/or assumed ACM.
- 5) Ensure the availability of the management plans for inspections and re inspections and provide notification of such availability.
- 7. Consider if any conflict of interest may arise from the interrelationship between accredited personnel and others that could affect the designation of a person to carry out the LEA's responsibilities.
- 8) Designated a person to ensure these responsibilities are implemented.

General Building Inspection Observations

The building inspection is conducted by a qualified and State of Iowa licensed Asbestos Inspector. The purpose of a building inspection is to identify existing building materials that are asbestos-containing materials (ACM). If the inspection is conducted in an occupied building, the Inspector is sometimes denied accessibility to all building areas and materials; i.e., the Inspector can not cut through floor coverings or walls, remove quarry tiles, etc. There are many situations where ACM are concealed in wall cavities and other non-accessible areas, such as tunnels, crawl spaces, above ceilings, pipe chases, under various floor coverings, etc. When these situations occur in construction, renovation, and/or demolition, etc., materials in these areas shall be treated as ACM and handled as such by qualified and licensed asbestos personnel. If suspect material is discovered or damaged during the course of activities, the material shall be considered and treated as ACM so no further fiber release will occur. The following are areas that may be inspected.

- 1. Tunnels and Crawl Spaces: During the inspection process, the Inspector attempts to check tunnels and crawl spaces for ACM and the degree of damage to the materials. In most cases, quantification of ACM in these areas is impossible due to the inaccessibility to these areas. In addition, these areas may fall under: "Confined Space Regulations". Due to the congestion in tunnels and crawl spaces, obtaining an accurate quantification for mudded joints, pipe wrap, etc. is almost impossible. The Inspector will quantify ACM only in accessible tunnels and crawl spaces, and estimate the quantities in the inaccessible areas. Some reasons for inaccessibility are as follows: flooded areas, pipe congestion, asbestos and other debris, electrical hazards, confined spaces, unknown gas emissions, low ceilings, etc.
- 2. Boilers and Thermal System Insulation: Interior portions of boilers, heaters, storage tanks, etc. are not always accessible. Materials in these areas will be treated as ACM. Areas of concern are packing inside boiler doors and liners. Use extreme care and properly trained personnel when handling theses types of materials. Some boilers have insulated metal jackets over fiberglass or ACM. Thermal system insulation can be found in many different forms; i.e., air cell, preformed mag block, millboard, etc. All mudded joints on thermal and domestic water systems, etc. will be considered as ACM. All fiberglass materials are excluded as suspect ACM.
- 3. **Debris:** Any area where damaged ACM are found may and usually have debris in the general area of the damaged material. These areas shall be treated with the utmost care even during the inspection and quantification process. The Inspector considers any exposure to this type of material as a health threat.

- 4. State of Quantification: As a general rule, individual rooms or areas of estimation contain inherently more probability of an error than those groups of rooms or areas or an entire building. In other words, the aggregate tends to be more accurate than the sums of the individual parts. Therefore, when designing response actions (measurements, air samples, etc.), attention shall be given to ensure that quantification and proper methods are followed through careful analysis of the site by the project designer and the asbestos abatement contractor.
- 5. The Inspector may take some latitude in the presentation of the Inspection Report. When the Inspector has found floor tiles, linoleum, and/or carpeting listed he/she may or may not have adhesives listed. Adhesives have been known to contain asbestos and therefore, although not mentioned, it may be presumed to be ACM, listed or not. Testing of the adhesive prior to disturbing is recommended. The same is true for adhesives or mastics used to adhere linoleum to floors or counter tops. All troweled-on and/or sprayed-on surfacing materials; i.e., floor mastics, wall and ceiling surfacings, etc. are either suspected or presumed ACM unless sampled and analyzed to indicate that they are not ACM.
- 6. In the Inspection Report, certain items such as mudded joints (MJ) or metal doors (MD), etc. are listed as units or number of units; i.e. 10 MJ, 3 Damaged, which is an indication of count rather than square feet or linear feet. Most materials listed in the assessment are either listed as square feet or linear feet with these noted exceptions.
- 7. In the Assessment Process, there are additional codes such as ME and MG; ME representing miscellaneous electrical and MG representing miscellaneous gasket materials. Both of these codes are used to indicate materials that are unusual to the normal course of an assessment of the building. Miscellaneous electrical materials include old electrical wiring, switch boards, transite panels, etc. Miscellaneous gasket materials can be found between (thermal) valves, on boiler doors, between fittings, between molds, etc. These codes give the Inspector the ability to qualify materials which sometimes may not be considered as ACM.
- **8.** A Code Sheet is included with the Inspector's inspection and assessment report which informs the client as to the Homogeneous Codes that were used during the inspection and assessment process.
- 9. All Black Table Tops and counters are considered to contain asbestos unless they are wood.

ASBESTOS CODES

A = Assumed

ADH = Adhesive

APW = Air Cell Pipe Wrap

BP = Boiler Plaster

C = Ceiling

CAPS = Stair Treads

CQ = Can't Quantify CT = Ceiling Tiles

CT/12 = 12" Ceiling Tiles

DAM. = Damaged

DEB. = Debris

F = Friable

FE = Furnace Exhaust

FT = Floor Tiles

GASK = Gaskets

GYM = Gypsum

HOMO = Homogeneous

LINO = Linoleum

M = Miscellaneous Non Friable

MAC = Metal Asbestos Chimney

MATL. DESC. = Material

Description

MD = Metal Door

ME = Miscellaneous Electrical

MF = Miscellaneous Friable

MJ = Mudded Joint

NC = Nose Cap

NF = Non Friable

P or PH = Previous History

PP = Patched Plaster/Drywall

PSA = Sand Plaster

PSM = Smooth Plaster

S = Sample/Samples/Sampled

SCT = Suspended Ceiling Tiles

SR = Sample Result

ST = Storage Tank

SU = Surfacing

T = Thermal

Thermal Pipe Measurement = Linear Feet

TR = Transite

TSI = Thermal System Insulation

VC = Vibration Cloth

VDW = Vinyl Covered Drywall

W = Walls

WD = Wood Door

N = North

S = South

E = East

W = West

- 1. All Metal Doors are listed by quantities, example 3 = 3 metal doors.
- 2. All Mudded Joints are listed by quantities of MJ, not sizes.
- 3. All Pipe Wrap materials are listed in linear feet.
- 4. All other measurements are square feet unless stated elsewhere.
- 5. Sample Results: N = Not Considered Asbestos Containing Material

Y = Considered Asbestos Containing Material

N/A = Not Analyzed

<1% = Contains less than 1% Asbestos Containing Material

>1% = Contains more than 1% Asbestos Containing Material

- 6. All Adhesives are considered Asbestos Containing Material which can't be quantified Non Friable ACM.
- 7. All Seals and Gaskets are considered Asbestos Containing Material which can't be quantified Non Friable ACM.

Anamosa High School Anamosa, Iowa 52205 Anamosa Community School District 209 Sadie St.

THREE YEAR REINSPECTION

LOCAL EDUCATION AGENCY: Anamosa Community School District

FACILITY/BUILDING SITE: Anamosa High School

INSPECTOR/MANAGEMENT PLANNER: Thomas E. Haas

REINSPECTION DATE: November 2020

REASSESSMENT DATE: November 2020

building materials and suspected asbestos containing building materials that were identified during the initial inspection have In accordance with the requirements of the Asbestos Hazard Emergency Response Act (AHERA), asbestos containing been reinspected, reassessed, and appropriate response actions have been determined.

The existing management plan has been updated to reflect any changes.


Note(s):

1. Refer to prior Reinspections for additional information.

Roof drains tested and are non-asbestos-results enclosed in 2014 re inspection report.

Extensive testing was done prior to the 2014 renovation and new addition. Results enclosed in 2014 Re inspection report.

Foner area apoleso 7-11



ų,

Facility: Anamosa High School Address: 209 Sadie Street Page: 1

Lower Gym Area

Inspector: Thomas E. Haas

of a system containing ACM as: T = Thermal, S = Surfacing, M = Miscellaneous), Area =Quantity/Count, DAM MATL. DESC. = Material Description, HOMO UNIT = Homogeneous Unit (HOMO UNIT = A system or part

				ely					Addition of the state of the st								
Vinyl base adhesive in the original building contains asbestos Caulking – area where glass sets into door frames and interior and exterior window frames contains as	Caulking around interior window frames- original building	All Black sinks, table tops and counters throughout the original building	Ali mudded joints on pipe lines contains asbestos – roof drains contains no asbestos	All metal doors may contain asbestos inside them if rated as fire doors- Door are not listed separal	Fascia on the exterior overhangs covered with metal – transite?				All asbestos mudded joints abated 2014	No asbestos based on extensive sampling and abatement on this level							
Throughout original building					Outside building				Lower level locker	complex							
	out original	Out original Caulking – area where glass sets into door frames and interior and exterior window frames contains asbestos Caulking around interior window frames- original building	Out original Caulking – area where glass sets into door frames and interior and exterior window frames contains asbestos Caulking around interior window frames- original building All Black sinks, table tops and counters throughout the original building	Out original Caulking – area where glass sets into door frames and interior and exterior window frames contains asbestos Caulking around interior window frames- original building All Black sinks, table tops and counters throughout the original building All mudded joints on pipe lines contains asbestos – roof drains contains no asbestos	Out original Caulking – area where glass sets into door frames and interior and exterior window frames contains asbestos Caulking – area where glass sets into door frames and interior and exterior window frames contains asbestos Caulking around interior window frames- original building All Black sinks, table tops and counters throughout the original building All mudded joints on pipe lines contains asbestos – roof drains contains no asbestos All metal doors may contain asbestos inside them if rated as fire doors- Door are not listed separately	Out original Caulking – area where glass sets into door frames and interior and exterior window frames contains asbestos Caulking around interior window frames- original building All Black sinks, table tops and counters throughout the original building All mudded joints on pipe lines contains asbestos – roof drains contains no asbestos All metal doors may contain asbestos inside them if rated as fire doors- Door are not listed separately Fascia on the exterior overhangs covered with metal – transite?	Out original Caulking – area where glass sets into door frames and interior and exterior window frames contains asbestos Caulking around interior window frames- original building All Black sinks, table tops and counters throughout the original building All mudded joints on pipe lines contains asbestos – roof drains contains no asbestos All metal doors may contain asbestos inside them if rated as fire doors- Door are not listed separately Fascia on the exterior overhangs covered with metal – transite?	Out original Vinyl base adhesive in the original building contains asbestos Caulking – area where glass sets into door frames and interior window frames contains asbestos Caulking around interior window frames- original building All Black sinks, table tops and counters throughout the original building All mudded joints on pipe lines contains asbestos – roof drains contains no asbestos All metal doors may contain asbestos inside them if rated as fire doors- Door are not listed separately Fascia on the exterior overhangs covered with metal – transite?	Out original Caulking – area where glass sets into door frames and interior and exterior window frames contains asbestos Caulking – area where glass sets into door frames and interior and exterior window frames contains asbestos Caulking around interior window frames - original building Ali Black sinks, table tops and counters throughout the original building Ali mudded joints on pipe lines contains asbestos – roof drains contains no asbestos Ali metal doors may contain asbestos inside them if rated as fire doors- Door are not listed separately Fascia on the exterior overhangs covered with metal – transite?	out original Caulking – area where glass sets into door frames and interior and exterior window frames contains asbestos Caulking – area where glass sets into door frames and interior and exterior window frames contains asbestos All Black sinks, table tops and counters throughout the original building All mudded joints on pipe lines contains asbestos – roof drains contains no asbestos All metal doors may contain asbestos inside them if rated as fire doors- Door are not listed separately Fascia on the exterior overhangs covered with metal – transite? Vel locker All asbestos mudded joints abated 2014	Out original Caulking – area where glass sets into door frames and interior and exterior window frames contains asbestos Caulking – area where glass sets into door frames and interior and exterior window frames contains asbestos Caulking around interior window frames contains asbestos All Black sinks, table tops and counters throughout the original building All medded joints on pipe lines contains asbestos – roof drains contains no asbestos All medal doors may contain asbestos inside them if rated as fire doors – Door are not listed separately Fascia on the exterior overhangs covered with metal – transite? All asbestos mudded joints abated 2014 No asbestos based on extensive sampling and abatement on this level	Out original Caulking – area where glass sets into door frames and interior and exterior window frames contains asbestos Caulking around interior window frames - original building All Black sinks, table tops and counters throughout the original building All mudded joints on pipe lines contains asbestos – roof drains contains no asbestos All metal doors may contain asbestos inside them if rated as fire doors- Door are not listed separately Fascia on the exterior overhangs covered with metal – transite? All asbestos mudded joints abated 2014 No asbestos based on extensive sampling and abatement on this level	Out original Caulking – area where glass sets into door frames and interior and exterior window frames contains asbestos Caulking around interior window frames ontains asbestos Caulking around interior window frames ontains asbestos All Black sinks, table tops and counters throughout the original building All mudded joints on pipe lines contains asbestos – roof drains contains no asbestos All metal doors may contain asbestos inside them if rated as fire doors- Door are not listed separately Fascia on the exterior overhangs covered with metal – transite? All asbestos based on extensive sampling and abatement on this level No asbestos based on extensive sampling and abatement on this level	Out original Caulking – area where glass sets into door frames and interior and exterior window frames contains asbestos Caulking around interior window frames contains asbestos Caulking around interior window frames contains asbestos All Black sinks, table tops and counters throughout the original building All metal doors may contain asbestos inside them if rated as fire doors. Door are not listed separately Fascia on the exterior overhangs covered with metal – transite? All asbestos based on extensive sampling and abatement on this level No asbestos based on extensive sampling and abatement on this level	Out original Vinyl base adhesive in the original building contains asbestos Caulking – area where glass sets into door frames and interior and exterior window frames contains asbestos Caulking around interior window frames - original building All Black sinks, table tops and counters throughout the original building All mudded joints on pipe lines contains asbestos — roof drains contains no asbestos All metal doors may contain asbestos inside them if rated as fire doors- Door are not listed separately Fascia on the exterior overfrangs covered with metal – transite? All asbestos based on extensive sampling and abatement on this level No asbestos based on extensive sampling and abatement on this level	out original Caulking – area where glass sets into door frames and interior window frames contains asbestos Caulking around interior window frames- original building All Black sinks, table tops and counters throughout the original building All Black sinks, table tops and counters throughout the original building All metal doors may contain asbestos inside them if rated as fire doors. Door are not listed separately Fascia on the exterior overhangs covered with metal – transite? All asbestos mudded joints abated 2014 No asbestos based on extensive sampling and abatement on this level No asbestos based on extensive sampling and abatement on this level	Out original Caulking – area where glass sets into door frames and interior and exterior window frames contains asbestos Caulking around interior window frames- original building Ali Black sinks, table tops and counters throughout the original building Ali metal doors may contain asbestos inside them if rated as fire doors- Door are not listed separately Fascia on the exterior overhangs covered with metal – transite? All asbestos muddled joints abated 2014 No asbestos based on extensive sampling and abatement on this level

Facility: Anamosa High School Address: 209 Sadie Street

Lower Level

Inspector: Thomas E. Haas

of a system containing ACM as: T = Thermal, S = Surfacing, M = Miscellaneous), Area =Quantity/Count, DAM MATL. DESC. = Material Description, HOMO UNIT = Homogeneous Unit (HOMO UNIT = A system or part

¥												
Ā												
MISC				uc						Mudded joints above SCT	Mudded joints	
본				w additi						×	×	
щ				ding ne								
SR				rt of ad						Υ	≻	
တ				. as ba						PH	×	
⋖				s demo								
DAM.				Green house was demo. as part of adding new addition						0	0	
AREA				Gree						4	11	-
HOMO UNIT	•									T2	T2	
MATL. DESC.										ſΜ	MJ	
ROOM		Green House	By Vo. Ag shop see	Inspection results in 2014 re inspection						Restroom (FFA)	27A Storage by FFA rest room	
Š.		 9							 	27	27A	

Facility: Anamosa High School Address: 209 Sadie Street

Lower Level

Inspector: Thomas E. Haas

of a system containing ACM as: T = Thermal, S = Surfacing, M = Miscellaneous), Area = Quantity/Count, DAM = Damaged, A = Assumed, S = Sampled, SR = Sample Result, F = Friable, NF = Non Friable, MISC = Miscellaneous, FA = Functional Area where HOMO Units are located, HA = Hazardous Assessment (1 - 7, with 7 being the worst). MATL. DESC. = Material Description, HOMO UNIT = Homogeneous Unit (HOMO UNIT = A system or part

7 being th													
- 7, with	Ψ												
sment (1	FA												
FA = Functional Area where $HOMO$ Units are located, $HA = Hazardous$ Assessment (1 - 7, with 7 being th	MISC	Metal door In Closet	Mudded joints on thermal	Mudded joints on heating Above SCT		Mudded joints	Could not locate 2020, may have been abated during renovation						
O Units	۲	×		×		×	bated						
e HOM	L		yes				peen s						
rea whe	SR		×	 >		yes	have						
xional A	တ			PH		×	, may						
√ = Func	∢	×				ļ	2020				 	 	
F4	DAM.	0	0	0		0	ot locate						
	AREA	_	ω	27		10	Could						
	HOMO UNIT	M10	T2	T2		T2							
	MATL. DESC.	MD	MJ	ſW		ſW							
	ROOM	Closets 4		Hall	Outside Room 12-Vo-Ag	Room 16							
	NO.	29	29A	 <u>ب</u>		31a	*******	 					

Facility: Anamosa High School Address: 209 Sadie Street Page: 4

Main Level

Inspector: Thomas E. Haas

MATL. DESC. = Material Description, HOMO UNIT = Homogeneous Unit (HOMO UNIT = A system or part

of a system containing ACM as: T = Thermal, S = Surfacing, M = Miscellaneous), Area = Quantity/Count, DAM = Damaged, A = Assumed, S = Sampled, SR = Sample Result, F = Friable, NF = Non Friable, MISC = Miscellaneous, FA = Functional Area where HOMO Units are located, HA = Hazardous Assessment (1 - 7, with 7 being the worst).

Η	} 												
Ā													
MISC			There is some adhesive residue where 12: ceiling tiles abated from the concrete block walls	Vinyl base board adhesive throughout -sample results in 2014 re inspection	3"Thick Wood Door - one door was removed					Mudded joints on heating Above SCT	Hall and Electric Room metal door		
ĸ			rom the	n 2014	×					×	×		
u.			abated f	results i									
S R		1	g tiles a	ample		nge				>			
ဟ			2: ceilin	ghout -s		ient lou				H			
4			where 1	e throug	×	ow stud	<u> </u>				×		
DAM.			e residue v	rd adhesiv	0	Vocal music now student lounge				0	0		
AREA			ne adhesiv	yl base boa	₹	Λος				21	က		
HOMO			here is sor	Vin	M14					T2	M10		·
MATL. DESC.					MD					ſW	QW		
ROOM		Band area/ vocal music			Hall A by band / vocal music practice	rooms				Hall B between band and gym			
Š					35			 		04	4		:

Facility: Anamosa High School Address: 209 Sadie Street Page: 5

Main Level

MATL. DESC. = Material Description, HOMO UNIT = Homogeneous Unit (HOMO UNIT = A system or part

of a system containing ACM as: T = Thermal, S = Surfacing, M = Miscellaneous), Area = Quantity/Count, DAM Inspector: Thomas E. Haas= Damaged, A = Assumed, S = Sampled, SR = Sample Result, F = Friable, NF = Non Friable, MISC = Miscellaneous, FA = Functional Area where HOMO Units are located, HA = Hazardous Assessment (1 - 7, with 7 being the worst).

2												
¥												
FA												
SR F NF MISC FA HA	Mudded joints on heating							Mudded joints on heating Above SCT				
Ŗ	×							×				
ட												
S	>							>				
တ	PH			:				PH				
∢									·			
DAM.	ო							0				
AREA	മ							31				
HOMO UNIT	T2							T2				
MATL. DESC.	ſΨ							MJ				
ROOM	Storage Areas C. (2)	Gym storage				Hall C.	Main hall by kitchen	Lunch area				
Ö.	 45		-					57				

Facility: Anamosa High School Address: 209 Sadie Street Page: 6

Main Level

Inspector: Thomas E. Haas

Facility: Anamosa High School Address: 209 Sadie Street Page: 7

Main Level

Inspector: Thomas E. Haas

	_	<u> </u>	1 - 1	T			ïI .		I	I	ſ	1	 т	η		,	Т	т—
4																		
π A																		
MISC	Mudded joint above ceilings	his is area where small green house was attached. Green house demo. as part of new addition			Transite Black Tops		Mudded joints above SCT		Mudded joints Above SCT					Mudded joints Above SCT	Part abated in 2014	Mudded joints Above SCT	past 112 and 108 to rest rooms were abated 2014	
Z		e demo			×		×		×					×		×	oms we	
Щ		n house															rest ro	
S. R.	>	d. Gree			yes		yes		>					>		>	1 108 to	
တ	×	attache			×		×		ЬН					표		표	112 and	
∢		e was															o past	
DAM.	0	green hous					0		0					%0		0	m room 120	
AREA	10	here small			Aii		80		7					29		22	Mudded joints from room 120	
HOMO	TSI	s is area w			6W		TSI		72					72		12	Mudde	
MATL. DESC.	ſΨ	<u>F</u>			TRP		MJ		ſΨ					ΓW		ſΨ		
ROOM	Storage room between	2 art rooms			Art	Room 124 &122	Room 124		Room 126 English					Hall E	Outside room 120	T = E	Outside 112 and 108	
NO.	29				89				72					75		76		

Facility: Anamosa High School Address 209 Sadie Street Page: 8

Main level Date: Jan 14, 08 Inspector: Thomas E. Haas

ROOM	MATL.	HOMOH	О П А	2 C	<	U	0	U	2	(Ĭ	=
78 Storage E	S N N N	<u> </u>	4	0	[H	≨ ≻	-	×	Mudded joints Above SCT	5	Ĕ
Kitchen area												
Restroom 1	M	T2	4	0		PH	>		×	Mudded joints Above SCT		
Kitchen area												
Soffit 5	ΩW	M10	~-		×				×	Metal door Exit		
By kitchen												
Food Storage	MD	M10	1		×				×	Metal door on Freezer		
									:			
Dish Washer	ſΜ	12	21	0		ЬН	>		×	Mudded joints Above SCT		
										debris on ceiling tiles non asbestos roof drain		
Kitchen	MD	M10	-		×				×	Cooler		
	M	T2	12	<10%		×	>	×		Mudded joints on heat above SCT - back wall above SCT	88	4
Electric 1 -	MD	M10	-	0	×				×	Metal door		
Custodian's office												
				Σ	Mudded joints abated 2014	oints ab	ated 20	4				

Facility: Anamosa High School Address:209 Sadie Street

Main level

Inspector: Thomas E. Haas

FA	-															
MISC					Yellow linoleum may be under new flooring?	Mudded joints above SCT	Mudded joints Above SCT		Mudded joints above SCT		Mudded joints		Mudded joints Above SCT		Mudded joints Above SCT	
Z				ļ	×	×	×		×		×		×		×	_
111								<u> </u>		_	_	_	ļ		-	
SR				ļ		>	>		>		<u> </u>		>		<u> </u>	$\left \right $
ဟ			<u> </u>			ЬН	 품		표		표	ļ	표		H	
4			 ļ	ļ	×					ļ				ļ	ļ	
DAM.					 -	0	0		0		0		0		0	
AREA					768	25	13		11		4		33		_	
HOMO					M15	T2	12		12		12		T2		72	
MATL. DESC.					ONII	ſМ	ΓIΜ		CIM		M		ſW		LM	
ROOM					Home Economics		Hall G	Outside Home EC	Boys A	By Home Ec	Utility	By Home Ec	100 Girls A	By Home Ec	Faculty Restroom 1	
NO.		 	 1		 92	96	 97		86		66 66		100		101	_

Facility: Anamosa High School Address: 209 Sadie Street Page: 10

Main Level

Inspector: Thomas E. Haas

of a system containing ACM as: T = Thermal, S = Surfacing, M = Miscellaneous), Area =Quantity/Count, DAM MATL. DESC. = Material Description, HOMO UNIT = Homogeneous Unit (HOMO UNIT = A system or part

¥.												
Ę												
MISC				Mudded joints Above SCT	Could not locate 2020 & 2017							
Z			 	×								
旺												
SR				>								
ဟ				ፗ				 				
∢			 				 					
DAM.				0								
AREA				7								
HOMO				T2								
MATL. DESC.		***************************************		ſW								
ROOM				106 Hall H	Outside 136 & 138							
NO.				106		108						

Facility: Anamosa High School Address: 209 Sadie Street Page: 11

Main level

Inspector: Thomas E. Haas

of a system containing ACM as: T = Thermal, S = Surfacing, M = Miscellaneous), Area =Quantity/Count, DAM MATL. DESC. = Material Description, HOMO UNIT = Homogeneous Unit (HOMO UNIT = A system or part

FA HA	\vdash													
MISC	Mudded joints Above SCT		Mudded joints Above SCT		***************************************	Drywall compound	Drywall compound is located above the suspended ceiling tiles where sliding doors are located drywall is non asbestos						PAYANTER PAYANTO	
L Z	×		×	;	×	×	ig tiles i							
Щ	<u> </u>						d ceilin				 		_	L
S. R.	<u></u>		>			Yes	endec s non			 				_
ဟ	H		표			 ×	susp wall is				 		ļ 	
∢				,	×	<u></u>	ve the							L
DAM.	0		0	C	>	0	ated above the suspended ceiling til							
AREA	5		10	(7	<u></u>	nd is loc							
HOMO UNIT	T2		T2		2	Misc	nodwoo					•		_
MATL. DESC.	ſΜ		ſΨ	Ę	<u></u>	DWC	Drywall							
ROOM	114 RR B Girls	By main office	Boy's RR B	2 = 0	ر الم	Room 136, 138,140		······································						

Facility: Anamosa High School Address: 209 Sadie Street Page: 12

Exterior

Inspector: Thomas E. Haas

of a system containing ACM as: T = Thermal, S = Surfacing, M = Miscellaneous), Area =Quantity/Count, DAM MATL. DESC. = Material Description, HOMO UNIT = Homogeneous Unit (HOMO UNIT = A system or part

~	≦	<u> </u>	Ţ	Π	T				T		<u> </u>		<u> </u>	<u> </u>	Γ		<u> </u>	
Д	-		-		-	\vdash	+-											-
Ц	-		70	├	ğ	1	-			-		ļ				-	ļ. <u> </u>	
Z Z			Letter of Exclusion enclosed		These small storage buildings are located north of the school at the high school football practice field and another location													
브	:				t the hi			İ										
п	-				school a													
C.					of the so												-	
Ø,					d north													
⋖					e locate													
DAM.					uildings are													
AREA					all storage t													
HOMO					These sma													
MATL. DESC.	None		Exempt		euou													
ROOM	Wood Storage		New Fitness Center		Storage buildings (3)													
Ö.																		



December 16, 2016

Anamosa Community School District ATTN: Tom Rogers 200 South Garnavillo Street Anamosa, Iowa 52205-1900

RE: Anamosa High School Additions & Renovations

Dear Tom:

The Contract Documents did not specify asbestos containing materials as a building material in the above referenced project. To the best of our knowledge, there were no asbestos containing materials used as a building material on this project.

Please retain this letter for your records.

Sincerely,

SHIVE-HATTERY, INC.

Andrew H. Iverson, AIA, ALEP

cc: Tom Henry, Septagon



November 23, 2004

Carol Lensing, Superintendent Anamosa Community School District 200 South Garnavillo Street Anamosa, IA 52205

Re: New Fitness Center/ Wrestling Facility

Dear Carol:

Please be advised, that to the best of our knowledge, there were no products containing asbestos materials either specified or installed in the construction of the aforementioned project for the portions of the project for which we were responsible.

If you have any further questions regarding this subject, please contact me directly.

Sincerely

Dale R Port

314 E. 4th Street Waterloo, IA 50703-4704 fel: 319.234.1515

fax: 319.234.1517

Now Central Administration and Former Middle School Anamosa, Iowa 52205 200 S. Garnavillo St. Maintenance

Anamosa Community School District

THREE YEAR REINSPECTION

LOCAL EDUCATION AGENCY: Anamosa Community School District

FACILITY/BUILDING SITE: Old Anamosa Middle School

INSPECTOR/MANAGEMENT PLANNER: Thomas E. Haas

REINSPECTION DATE: November 2020

REASSESSMENT DATE: November 2020

building materials and suspected asbestos containing building materials that were identified during the initial inspection have In accordance with the requirements of the Asbestos Hazard Emergency Response Act (AHERA), asbestos containing been reinspected, reassessed, and appropriate response actions have been determined.

The existing management plan has been updated to reflect any changes.

Note(s):

The old middle school was demo 2014. Old maintenance shop remains as well as Central Administration Complex 1. Refer to prior Re inspections for additional information.

Letter of Exclusion enclosed for Administration building

Anamosa Community School District INSPECTION FORM

Facility: Anamosa

Address: Middle School

Maintenance building

= Damaged, A = Assumed, S = Sampled, SR = Sample Result, F = Friable, NF = Non Friable, MISC = Miscellaneous, FA = Functional Area where HOMO Units are located, HA = Hazardous Assessment (1 - 7, with 7 being the worst). of a system containing ACM as: T = Thermal, S = Surfacing, M = Miscellaneous), Area = Quantity/Count, DAM MATL. DESC. = Material Description, HOMO UNIT = Homogeneous Unit (HOMO UNIT = A system or part ¥ 4 FΑ MISC Extensive sampling was done and asbestos containing materials were abated Letter of Exclusion enclosed S SR F NF 4 DAM. AREA Inspector: Thomas E. Haas MATL. HOMO DESC. UNIT NONE Administration Building 118 Maintenance bldg. ROOM

ANDALL J. McCAULLEY, Ed.D Superintendent of Schools Phone 319-462-4321 FAX 319-462-4322

August 28, 1998

Mr. Wolfgang Brandner Environmental Protection Agency 726 Minnesota Avenue Kansas City, Kansas 66101

Re: Anamosa Community School District

Dear Mr. Brandner:

Enclosed you will find a statement for the exclusion of our new building additions located at: 1. West Middle School Annex
2. Strawberry Hill Elementary Addition

In addition, I have enclosed a diagram of the additions for which we are filing this exclusion.

A copy of this letter, a copy of the architect's statement, and the enclosed diagram shall be placed in the following management plans:

(a) Superintendent's copy of the Management Plan.

- (b) West Middle School administration office copy of the Management Plan.
- (c) Strawberry Hill Elementary School administration office copy of the Management Plan.
- (d) Designated person copy of Management Plan.

The above building and addition are located at:

- 1. West Middle School Annex: 200 South Garnavillo St., Anamosa, IA
- 2. Strawberry Hill Elementary Addition: 203 Hamilton, Anamosa, IA

We will be utilizing this space by the 1998-99 school year.

If you have any additional questions, please feel free to contact me.

Sincerely,

Randall J. McCaulley

Superintendent

cc: Management Plan Copies

1. M. Cull



August 31, 1998

Dr. Randall J. McCaulley Superintendent of Schools Anamosa Community School District 200 South Garnavillo Street Anamosa, IA 52205

Re: Strawberry Hill Elementary School Additions and Remodeling Anamosa Community School District, Anamosa, IA

Dear Dr. McCaulley:

Please be aware that according to Iowa law for schools we must document the fact that there was no asbestos containing material specified on the above subject project. My understanding of the law is this refers to Public School Rule #40 C.F.R. Section 763.99 (a) (7).

Therefore, please be informed that we have not specified as a part of the new construction, any asbestos containing material. Also, to the best of our knowledge, we are not aware of any asbestos containing material that has been used in the construction of this same project.

Please do an hesitate to contact me if you have any further questions regarding this matter.

Sincere

GRIMF PORT-JONES-SCHWERDTFEGER/ARCHITECTS, INC.

Dale 1 Port, AIA

1.1

fax fom Haas - Haase 5, Ltd.

Strawberry Hill
Elementary School
203 Hamilton Court
Anamosa, Iowa 52205

Anamosa Community School District

THREE YEAR REINSPECTION

LOCAL EDUCATION AGENCY: Anamosa Community School District

FACILITY/BUILDING SITE: Strawberry Hill Elementary School

INSPECTOR/MANAGEMENT PLANNER: Thomas E. Haas

REINSPECTION DATE: November 2020


REASSESSMENT DATE: November 2020

building materials and suspected asbestos containing building materials that were identified during the initial inspection have In accordance with the requirements of the Asbestos Hazard Emergency Response Act (AHERA), asbestos containing been reinspected, reassessed, and appropriate response actions have been determined.

The existing management plan has been updated to reflect any changes.

Note(s)

- 1. Refer to prior Re inspections for additional information.
- Prior sample results located in 2014 AHERA Re Inspection report.



INSPECTION FORM Anamosa Community School District

Address: Strawberry Hill Facility: Anamosa Page: 1

Inspector: Thomas E. Haas

of a system containing ACM as: T = Thermal, S = Surfacing, M = Miscellaneous), Area =Quantity/Count, DAM MATL. DESC. = Material Description, HOMO UNIT = Homogeneous Unit (HOMO UNIT = A system or part

= Damaged, A = Assumed, S = Sampled, SR = Sample Result, F = Friable, NF = Non Friable, MISC = Miscellaneous, FA = Functional Area where HOMO Units are located, HA = Hazardous Assessment (1 - 7, with 7 being the worst).

	_	т	1	 	Γ		1		ı		Г	 	T	1	 r
4															
Ā															
MISC	Adhesive behind 12"	Ceiling tiles- above SCT original building	Abated 2014		North side removed 98	Transite		Ceiling tiles abated 2014			New tiles over Old floor tiles and adhesive				
Ш Z	×				×						×				
ш		floor													
S	Yes	ular to													
Ø		endic							 	•					
∢		" per			×						×				
DAM.	0	ng tiles 12			0						0				
AREA	lla B	Adhesive behind ceiling tiles 12" perpendicular to floor			50						298				
HOMO LINIT	Misc	esive be			M9						M2				
MATL. DESC.	ADH	Adi	Pipe wrap		TR						Ħ				
ROOM	Throughout original	building	Food Storage		Canopy Soffits			Room 207			Nurse Complex				
NO.			ო		ഹ			 <u> </u>			<u>—</u> ച				

Anamosa Community School District INSPECTION FORM

Address: Strawberry Hill Facility: Anamosa Page: 2

Inspector: Thomas E. Haas

MAIL. DESC. = Material Description, HOMO UNIT = Homogeneous Unit (HOMO UNIT = A system or part

= Damaged, A = Assumed, S = Sampled, SR = Sample Result, F = Friable, NF = Non Friable, MISC = Miscellaneous, FA = Functional Area where HOMO Units are located, HA = Hazardous Assessment (1 - 7, with 7 being the worst). of a system containing ACM as: T = Thermal, S = Surfacing, M = Miscellaneous), Area =Quantity/Count, DAM

	ROOM	MATL. HOMO DESC. UNIT	HOMO UNIT	AREA	DAM.	∢	Ø	SR	щ	뿔	MISC	Ą	¥
	4th B Now 208/210	FT	M2	400	ဗ	×				×	North side abated and carpet		
											Floor tiles and adhesive under carpet		
	LD Now 204/206	Ŧ	M2	400	0	×				×	North side abated		
											Floor tiles and adhesive		
	Canopy 2	TR	6W	90	0	×				×	Transite Ceiling		
	By Front Entrance	Transite	e above t	Transite above the ceiling	in reception area was once exterior	otion a	rea w	as ond	e exte	erior			
	Library	ΓW									Testednot asbestos		
	Now Computer Lab									<u> </u>			
	Boiler room	Exhaust		4	0	×				×	Near Roof on Flue		
		MD	M10	2	0	×				×	Label B		
	Exterior buildings												
	•			Vinyl sid	ded 8' x 1	2, por	table	puildin) 0 0	əst sic	Vinyl sided 8' x 12' portable building – west side of school - none		
			Two	small st	orage bui	Iding I	ocate	d at sc	ftball	field b	Two small storage building located at softball field behind the school - none		
					Single car garage -east of school -none	ar gal	rage -	east o	f scho	ğ	ne		
			Conc	ession st	and – sof	fball fi	eld –	west c	f scho	ol- le	Concession stand - softball field - west of school- letter of exclusion enclosed		
1													

Anamosa Community School District Strawberry Hill Elementary Anamosa, Iowa

Asbestos Letter of Exclusion Concession Stand

Behind the school at softball field

As an asbestos inspector, I state that the above buildings were built after October 12, 1988. No Asbestos Containing Building Materials were specified as building materials in any construction document for the buildings and to the best of my knowledge, no Asbestos Containing Building Materials were used as building materials in these buildings.

- 105 JON

Thomas E. Haas

5/2

Asbestos Inspector/ Management Planner Inspector number 17-7652 - State of Iowa

NDALL J. McCAULLEY, Ed.D Superintendent of Schools Phone 319-462-4321 FAX 319-462-4322

August 28, 1998

Mr. Wolfgang Brandner Environmental Protection Agency 726 Minnesota Avenue Kansas City, Kansas 66101

Re: Anamosa Community School District

Dear Mr. Brandner:

Enclosed you will find a statement for the exclusion of our new building additions located at: 1. West Middle School Annex
2. Strawberry Hill Elementary Addition

In addition, I have enclosed a diagram of the additions for which we are filing this exclusion.

A copy of this letter, a copy of the architect's statement, and the enclosed diagram shall be placed in the following management plans:

(a) Superintendent's copy of the Management Plan.

- (b) West Middle School administration office copy of the Management Plan.
- (c) Strawberry Hill Elementary School administration office copy of the Management Plan.
- (d) Designated person copy of Management Plan.

The above building and addition are located at:

- 1. West Middle School Annex: 200 South Garnavillo St., Anamosa, IA
- 2. Strawberry Hill Elementary Addition: 203 Hamilton, Anamosa, IA

We will be utilizing this space by the 1998-99 school year.

If you have any additional questions, please feel free to contact me.

Sincerely,

Randall J. McCaulley

Superintendent

cc: Management Plan Copies



GPJS ARCHITECTS

August 31, 1998

Dr. Randall J. McCaulley Superintendent of Schools Anamosa Community School District 200 South Garnavillo Street Anamosa, IA 52205

Re: Strawberry Hill Elementary School Additions and Remodeling Anamosa Community School District, Anamosa, IA

Dear Dr. McCaulley:

Please be aware that according to Iowa law for schools we must document the fact that there was no asbestos containing material specified on the above subject project. My understanding of the law is this refers to Public School Rule #40 C.F.R. Section 763.99 (a) (7).

Therefore, please be informed that we have not specified as a part of the new construction, any asbestos containing material. Also, to the best of our knowledge, we are not aware of any asbestos containing material that has been used in the construction of this same project.

Please do to hesitate to contact me if you have any further questions regarding this matter.


Sincere

GRIMF PORT-JONES-SCHWERDTFEGER/ARCHITECTS, INC.

Date 1 Port, AIA

[-1]

Fax Com Haas - Haaseb, Ltd.



Existing Room

il

Legend

(OVER)

Miscellaneous Locations

Anamosa Community School District

THREE YEAR REINSPECTION

LOCAL EDUCATION AGENCY: Anamosa Community School District

FACILITY/BUILDING SITE: Miscellaneous Locations

INSPECTOR/MANAGEMENT PLANNER: Thomas E. Haas

REINSPECTION DATE: November 2020

REASSESSMENT DATE: November 2020

building materials and suspected asbestos containing building materials that were identified during the initial inspection have In accordance with the requirements of the Asbestos Hazard Emergency Response Act (AHERA), asbestos containing been reinspected, reassessed, and appropriate response actions have been determined.

The existing management plan has been updated to reflect any changes.

Note(s): Refer to prior Re Inspections for additional information.

Locations Include the Following:

Football Field

Eden Field

Raider softball

Bus barn

Anamosa Community School District INSPECTION FORM

Facility: Football/Baseball Fields/Bus Barn Address: Anamosa, Iowa Page: 1

Inspector: Thomas E. Haas

of a system containing ACM as: T = Thermal, S = Surfacing, M = Miscellaneous), Area = Quantity/Count, DAM MATL. DESC. = Material Description, HOMO UNIT = Homogeneous Unit HOMO UNIT = A system or part

= Damaged, A = Assumed, S = Sampled, SR = Sample Result, F = Friable, NF = Non Friable, MISC = Miscellaneous, FA = Functional Area where HOMO Units are located, HA = Hazardous Assessment (1 - 7, with 7 being the worst).

5	5																	
, Y	2																	
O																		Metal Asbestos Chimney
ŭ Z														•				 ×
п	-													ļ				
S.																		
Ø,															L			
∢								e										×
DAM.								shed - noi						roof - none				1
AREA	one	None	s - None	- none	ed - none		none	ded storage		ne1.	- none	1. Broadcast concession - exempt		- one way				4
HOMO	1. Broadcast - None	2. Concession stand - None	3. Storage / restrooms - None	metal shed - none	5. 8 x 8 hip storage shed - none	1. Ticket booth - None	2. 8 x 12 Grey shed - none	hite vinyl si	ed- none	1. Dugouts (2) none1.	orage shed	st concessi	(Z) none	orage shed				M12
MATL. DESC.	1. Broad	2. Concess	3. Storage	4.8' x 12' r	5.8×8 hip	1. Ticket by	2.8×12G	3. 8 x 16 white vinyl sided storage shed - none	4. 4' x4' sh	1. Dugou	2. 8 x 12 storage shed - none	1. Broadca	2. Dugouts (2) none	3. White storage shed - one way roof - none				MAC
ROOM	Football field	anile side				Visitor side				Eden field		Raider softball				 		 Bus barn
S S																	 	

September 2004

To: To Whom it Concerns

Re: New concessions stand (12x20) at the Anamosa Community School District's softball field.

No asbestos containing building material was specified as a building material in any construction document for this building, or, to the best of my knowledge, no ACBM was used as a building material in the building.

5 6206

Sincerely,

Thomas E. Haas

6 New Middle School

410 Old Dubuque Road Anamosa, Iowa



6200 Autora Avenue Suite 210W Des Moines, IA 50322

o: 515/276-8097 f: 515/252-0514

September 5, 2014

Lisa Beames, Superintendent **Anamosa Community School District** 200 South Garnavillo Street Anamosa, Iowa 52205 lbeames@anamosa.k12.ia.us

Project Name:

Anamosa New Middle School

DLR Group Project No.:

11-07109-00

Re: Certification Statement

Dear Ms. Beames:

This letter is intended to serve as notice and certification that to the best of our Firm's knowledge, no asbestos was specified or used in the manufacture or fabrication of products and materials used in the construction of the above-referenced project.

If have any questions regarding this statement, please do not hesitate to contact our office.

Sincerely,

DLR Group, inc. (an Iowa Corporation)

Eric M. Beron, AIA, LEED AP

Architect | Principal

Orlando

Anamosa Community School District Junior High Site

Asbestos Letter of Exclusion

Sport Complex

- 1. Ticket booth
- 2. Baseball field 2 dugouts, broadcast above bleachers, pump house
- 3. Competition softball field 2 dugouts
- 4. Concession stand/restroom/storage between fields

As an asbestos inspector, I state that the above buildings were built after October 12, 1988. No Asbestos Containing Building Materials were specified as building materials in any construction document for the buildings and to the best of my knowledge, no Asbestos Containing Building Materials were used as building materials in these buildings.

Thomas E. Haas

Asbestos Inspector/ Management Planner Inspector number 17-7652 - State of Iowa

Anamosa Community School District Middle school Anamosa, Iowa

Asbestos Letter of Exclusion Garage Storage building

As an asbestos inspector, I state that the above buildings were built after October 12, 1988. No Asbestos Containing Building Materials were specified as building materials in any construction document for the buildings and to the best of my knowledge, no Asbestos Containing Building Materials were used as building materials in these buildings.

Thomas E. Haas Asbestos Inspector/ Management Planner Inspector number 17-7652 - State of Iowa P.O. Box 156

Dyersville, Iowa 52040

Phone 563-875-8300

haascoltd@yahoo.com

November 2020

Anamosa Community School District Sport Complex

At Middle School

Broadcast building - softball field

Per 763.99(a) A local education agency shall not be required to perform an inspection under 763.85(a) in any sampling area as defined in 40 CFR 763.103 or homogenous area of a school building where: an architect or an asbestos inspector signs a statement that no ACBM was specified as a building material in any construction documents for the building, or, to the best of his or her knowledge, no ACBM was used as a building material in the building for a building built after October 12, 1988.

This sign document will exempt this new building for inspections under the AHERA regulation. However it does not exempt it from complying with the NESHAP asbestos regulation.

Thomas E. Haas

State of Iowa license number: 20 - 3704